Water System Name: Bar Circle S Ranch		PWS ID No.: 1280010 RE	COLIFORM BACTERIA ANALYSIS REPORT			Laboratory Name: Accurate Testing Labs, LLC					
Collector: Jesse		Date Collecter 07/17/2023	d: County: Kootenai	CONTAMINANT ID# 3100			Phone	7950 Meadowlark Way Coeur d'Alene, ID 83815 Phone (208) 762 8378 Fax (208) 762 9082			
Report Results to:			Type of System: Public		W	Web site: www.accuratetesting.com					
Bar Circle S Ranch				Type of Sample:Compliance SampleLab Order No.:2023070317				E-mail: info@accuratetesting.com			
Leslie Rayner P.O. Box 3388							Lab EPA ID No: ID00912				
Coeur d'Alen				Water system info mu	st be fully filled	out or samples wil					
Phone: (208) 651-7769 Fax:			Water system info must be fully filled out or samples will not be run. Private samples do not need PWS# or Chlorine residual. Your sample will be analyzed for TOTAL			For PWS	For PWS only, if this is a repeat sample, mark the date of the ORIGINAL POSITIVE				
water.com,pv	@gemstate-wate vsreports@deq.i o@gemstate-wa	daho.gov,lisa@		COLIFORMS unless y							
Sample Number	Sample Type		Sample Location	-	Time Collected	Chlorine Residual ppm	Original Sample Date	Total Coliform Method:	E. Coli Method:		

Number			Collected	Sample Date	Method: 9223B-PA	Method: 9223B-PA
257290	RS-Routine Sample	19257 Ella Rd	13:25		Absent	Absent

Sample Transportation by (Name):	Jesse	Date/Time:	07/17/2023 14:10	Analyst: ME	Date Analyzed: 07/18/2023		
Sample Received by (Name):	JM	Date/Time:	07/17/2023 14:10	Supervisor: Rhena Cooper			
Remarks:				Date Reviewed and Printed: 07/18/23			