Water System Name: Bar Circle S Ranch			PWS ID No.: 1280010 RE	COLIFORM BACTERIA ANALYSIS REPORT CONTAMINANT ID# 3100				Laboratory Name: Accurate Testing Labs, LLC 7950 Meadowlark Way Coeur d'Alene, ID 83815 Phone (208) 762 8378 Fax (208) 762 9082		
Collector: Date Collected: 08/07/2023		l: County: Kootenai	Phone							
Report Results to:			Type of System: Public			Web site: www.accuratetesting.c		atetesting.com		
Bar Circle S Ranch				Type of Sample:	Sample: Compliance Sample			E-mail: info@accuratetesting.com		
Leslie Rayner P.O. Box 3388 Coeur d'Alene, ID 83816			Lab Order No.:	ab Order No.: 2023080163			Lab EPA ID No: ID00912			
			Water system info must be fully filled out or samples will not							
Phone: (208) 651-7769 Fax:			be run. Private samples do not need PWS# or Chlorine residual. Your sample will be analyzed for TOTAL			For PW	For PWS only, if this is a repeat sample, mark the date of the ORIGINAL POSITIVE			
E-Mail: leslie@gemstate-water.com,cole@gemstate- water.com,pwsreports@deq.idaho.gov,info@gemstate- water.com				COLIFORMS unless you specify analysis under Remarks. SAMPLE.						
Sample Number	Sample Type	S	Sample Location	-	Time Collected	Chlorine Residual ppm	Original Sample Date	Total Coliform Method: 9223B-PA	E. Coli Method: 9223B-PA	

16:30

Absent

Absent

258217

RS-Routine Sample

Amulet / Dolan Hydrant

Sample Transportation by (Name):	Jesse	Date/Time:	08/08/2023 12:20	Analyst: ME	Date Analyzed: 08/09/2023
Sample Received by (Name):	JM	Date/Time:	08/08/2023 12:20	Supervisor: Rhena Coc	per
Remarks:		Date Reviewed and Printed: 08/09/23			