Water System Name: Bar Circle S Ranch		PWS ID No.: 1280010 RE		
Collector: Zayne	Date Collected: 06/06/2024	County: Kootenai		
Report Results to: Bar Circle S Ranch Leslie Rayner P.O. Box 3388 Coeur d'Alene, ID 83816				
Phone: (208) 651-7769	Fax:			
Maily Isolia @ gamatata water sam cale @ gamatata				

E-Mail: leslie@gemstate-water.com,cole@gemstate-water.com,pwsreports@deq.idaho.gov,info@gemstate-water.com

## **COLIFORM BACTERIA**

## ANALYSIS REPORT

CONTAMINANT ID# 3100

Lab Order No.:	2024060153
Type of Sample:	Compliance Sample
Type of System:	Public

Water system info must be fully filled out or samples will not be run. Private samples do not need PWS# or Chlorine residual. Your sample will be analyzed for TOTAL COLIFORMS unless you specify analysis under Remarks. Laboratory Name:

## **Accurate Testing Labs, LLC**

7950 Meadowlark Way
Coeur d'Alene, ID 83815
Phone (208) 762 8378 Fax (208) 762 9082
Web site: www.accuratetesting.com
E-mail: info@accuratetesting.com

Lab EPA ID No: ID00912

For PWS only, if this is a repeat sample, mark the date of the ORIGINAL POSITIVE SAMPLE.

Sample Number	Sample Type			Original Sample Date	Total Coliform Method: 9223B-PA	E. Coli Method: 9223B-PA
268760	RS-Routine Sample	1383 W Garwood Rd	13:45		Absent	Absent

Sample Transportation by (Name):	Zayne	Date/Time:	06/06/2024 14:20	Analyst: RH	Date Analyzed: 06/07/2024
Sample Received by (Name):	JM	Date/Time:	06/06/2024 14:20	Supervisor: Rhena Co	oper
Remarks:		Date Reviewed and Printed: 06/07/24			